

duomed soft below knee



All measurements should be taken on the bare leg in centimetres.
Ensure that the tape measure is snug but not too tight.
Measurements should be taken when the leg is rested and not swollen.

Please consider that selecting the right size is very important.

circumference in cm		S	M	L	XL	XXL
calf	(eC)	28 - 34	32 - 38	36 - 42	40 - 46	44 - 50
ankle	(eB)	19 - 21	22 - 24	25 - 27	28 - 30	31 - 34